



MATCH these two as best as possible
 2x 6.79k resistors are better than
 1x 6.81k and 1x 6.82k

BEFORE turn on for the first time
 make sure this trim pot is set
 to COUNTERCLOCKWISE

2N73 MAIN PCB
 rev1.00